

MONUMENT RECORD
State of Indiana - County of Monroe

Section: 16


Township: 9 North

Range: 1 East

Corner ID: Ben So I-11

Monument Description & Remarks: Found 2" iron axle set by Mr. Fleener after survey done by Bledsoe, Tapp, and Rieggert.

References On File: Survey done by Ben Bledsoe, also Hanna Boundary survey by Lee Utt bk1 pg. 158 with file in the Surveyors office.



I, Kevin P. Enright, Monroe County Surveyor, hereby certify that this document was prepared under my direction in accordance with the provisions of Section 36-2-12-11 of the Indiana Code; and the above data is given under my hand and seal this 16th day of Dec., 1997.

Kevin P. Enright

Administered by the Monroe County Surveyor Review Board

Date: December 14, 2000

